


INTERTEK TESTING SERVICES

Report No.: HK11030630-1

Sample No.: 2/2



Bandedge Plot – Pursuant to FCC Part 15 Section 15. 227 / RSS-310 Section 3.8 Requirement