



# INTERTEK TESTING SERVICES

Report No.: HK11060534-1  
Sample No.: 1/2



Date: 11.JUN.2011 05:08:05




Date: 11.JUN.2011 05:08:20


**Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement  
Pursuant to RSS-210 Requirement**

# INTERTEK TESTING SERVICES

Report No.: HK11060534-1  
Sample No.: 1/2



Date: 11.JUN.2011 05:08:51



Date: 11.JUN.2011 05:09:14


**Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement  
Pursuant to RSS-210 Requirement**

Code: FCC15C\_d / Effective Date: 26 Jan 2010

( of )

# INTERTEK TESTING SERVICES

Report No.: HK11060534-1  
Sample No.: 1/2



Date: 11.JUN.2011 05:09:59

$$\begin{aligned} \text{Duty Cycle:} \\ &= \frac{2.34 \times 2 + 2 \times 1}{100} \text{ ms} \\ &= 0.0668 \end{aligned}$$

$$\begin{aligned} \text{Average Factor:} \\ &= 20 \log(0.0668) \\ &= -23.5 \text{ dB} \end{aligned}$$

**Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement  
Pursuant to RSS-210 Requirement**

Code: FCC15C\_d / Effective Date: 26 Jan 2010

( of )