




# **Annex C**


## **Out of Band Emissions**



### Uplink\_CDMA\_Lower\_1710 - 1755 MHz




### Uplink\_CDMA\_Lower\_1850 - 1915 MHz






### Uplink\_CDMA\_Lower\_698 - 716 MHz




### Uplink\_CDMA\_Lower\_776 - 787 MHz






### Uplink\_CDMA\_Lower\_824 - 849 MHz




### Uplink\_CDMA\_Upper\_1710 - 1755 MHz






### Uplink\_CDMA\_Upper\_1850 - 1915 MHz




### Uplink\_CDMA\_Upper\_698 - 716 MHz






### Uplink\_CDMA\_Upper\_776 - 787 MHz




### Uplink\_CDMA\_Upper\_824 - 849 MHz






### Uplink\_GSM\_Lower\_1710 - 1755 MHz




### Uplink\_GSM\_Lower\_1850 - 1915 MHz






### Uplink\_GSM\_Lower\_698 - 716 MHz




### Uplink\_GSM\_Lower\_776 - 787 MHz








### Uplink\_GSM\_Lower\_824 - 849 MHz




### Uplink\_GSM\_Upper\_1710 - 1755 MHz






### Uplink\_GSM\_Upper\_1850 - 1915 MHz




### Uplink\_GSM\_Upper\_698 - 716 MHz






### Uplink\_GSM\_Upper\_776 - 787 MHz




### Uplink\_GSM\_Upper\_824 - 849 MHz






### Uplink\_WCDMA\_Lower\_1710 - 1755 MHz




### Uplink\_WCDMA\_Lower\_1850 - 1915 MHz






### Uplink\_WCDMA\_Lower\_698 - 716 MHz




### Uplink\_WCDMA\_Lower\_776 - 787 MHz






### Uplink\_WCDMA\_Lower\_824 - 849 MHz




### Uplink\_WCDMA\_Upper\_1710 - 1755 MHz






### Uplink\_WCDMA\_Upper\_1850 - 1915 MHz




### Uplink\_WCDMA\_Upper\_698 - 716 MHz






### Uplink\_WCDMA\_Upper\_776 - 787 MHz




### Uplink\_WCDMA\_Upper\_824 - 849 MHz








### Downlink\_CDMA\_Lower\_1930 - 1995 MHz




### Downlink\_CDMA\_Lower\_2110 - 2155 MHz






### Downlink\_CDMA\_Lower\_728 - 746 MHz




### Downlink\_CDMA\_Lower\_746 - 757 MHz






### Downlink\_CDMA\_Lower\_869 - 894 MHz




### Downlink\_CDMA\_Upper\_1930 - 1995 MHz






### Downlink\_CDMA\_Upper\_2110 - 2155 MHz




### Downlink\_CDMA\_Upper\_728 - 746 MHz






### Downlink\_CDMA\_Upper\_746 - 757 MHz




### Downlink\_CDMA\_Upper\_869 - 894 MHz






### Downlink\_GSM\_Lower\_1930 - 1995 MHz




### Downlink\_GSM\_Lower\_2110 - 2155 MHz






### Downlink\_GSM\_Lower\_728 - 746 MHz




### Downlink\_GSM\_Lower\_746 - 757 MHz






### Downlink\_GSM\_Lower\_869 - 894 MHz




### Downlink\_GSM\_Upper\_1930 - 1995 MHz








### Downlink\_GSM\_Upper\_2110 - 2155 MHz




### Downlink\_GSM\_Upper\_728 - 746 MHz






### Downlink\_GSM\_Upper\_746 - 757 MHz




### Downlink\_GSM\_Upper\_869 - 894 MHz






### Downlink\_WCDMA\_Lower\_1930 - 1995 MHz




### Downlink\_WCDMA\_Lower\_2110 - 2155 MHz






### Downlink\_WCDMA\_Lower\_728 - 746 MHz




### Downlink\_WCDMA\_Lower\_746 - 757 MHz






### Downlink\_WCDMA\_Lower\_869 - 894 MHz




### Downlink\_WCDMA\_Upper\_1930 - 1995 MHz






### Downlink\_WCDMA\_Upper\_2110 - 2155 MHz




### Downlink\_WCDMA\_Upper\_728 - 746 MHz





### Downlink\_WCDMA\_Upper\_746 - 757 MHz



### Downlink\_WCDMA\_Upper\_869 - 894 MHz

