



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

February 9, 2004

RE: Qcom Technology Inc.

FCC ID: RUJ-Q802MIG

I have a few comments on the above referenced Application.

- 1) Please provide a new "Label Location" exhibit, as this exhibit shows the incorrect FCC ID.
- 2) Please provide a modular request letter for this application.

A handwritten signature in black ink, appearing to read "Timothy R. Johnson", is written over a light gray rectangular background.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.