

6th January 2006

Re. FCCID RV6HT840

To Who it may concern,

This is to confirm that the HT840 Handheld Marine transceiver has no user tuneable parts inside and therefore requires no alignment.

Signed:



Name:
Jim Rimington
Technical Manager

4 Elstree gate
Elstree Way, Borehamwood
Hertfordshire WD6 1JD
United Kingdom

Tel: +44 (0)20 8236 0032
Fax: +44 (0)20 8236 0082
Email: sales@entel.co.uk
www.entel.co.uk



Incorporated in the United Kingdom
Registration No: 3143328