



**To:**

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, Maryland 21046

**Subject:** FCC 15.203 Compliance, Non-Standard Antenna Connector Requirement

Gentlemen,

The Nortel Networks access point radios are available in versions that incorporate only internal antennas as well as a version that incorporates antenna connectors for connection to external antennas.

FCC ID: RVW2230	Model 2230
FCC ID: RVW2231	Model 2231

IC: 332R-2230	Model 2230
IC 332R-2231	Model 2231

These connectors used in these models are "Reverse TNC" connectors and are currently FCC 15.203 compliant.

Additionally, it is Nortel's intent that these IEEE 802.11 access point radios be professionally installed and NOT installed by the end user of the system.

If you have any questions, please do not hesitate to contact me at: [david@waitt.us](mailto:david@waitt.us) or (408) 832-7053

Sincerely,

A handwritten signature in black ink, appearing to read "David Waitt".

David Waitt  
Consultant representing Nortel Networks