

## Helen Zhao

---

**Subject:** FW: BridgeWave Communications, Inc. , FCC ID: RWM-GE60, Assessment NO.: AN05T4901, Notice#1



05U3500-1B FCC  
Report.pdf

From: Michael Heckrotte  
Sent: Wednesday, June 29, 2005 10:35 AM  
To: Helen Zhao  
Subject: RE: BridgeWave Communications, Inc. , FCC ID: RWM-GE60, Assessment NO.: AN05T4901, Notice#1

Helen,

#1 is a PDF conversion error.

#2 is a typo; the correct value is 0.0068 mW/cm^2.

Please see attached revised report.

Thanks,  
Mike

-----Original Message-----

From: Compliance Certification Services  
Sent: Wednesday, June 29, 2005 9:39 AM  
To: Helen Zhao  
Subject: BridgeWave Communications, Inc. , FCC ID: RWM-GE60, Assessment NO.: AN05T4901, Notice#1

Question #1: Test Report section 5.3: The table shows output power measurement, not the support equipment as the title suggested. Please update the test report.

Question #2: Test Report - Section 7.5 RF Exposure: Please explain why  $S=6.8\mu\text{W}/\text{cm}^2=0.068\text{mW}/\text{cm}^2$ .

Best Regards,  
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.