

N14509

Differences between old and new version

We hereby apply for class II permissive change of FCC ID: RX2N14509 due to the following changes:

- 1) Power Board:
PCB optimisation

- 4) Mother Board:
PCB optimisation

All the described changes don't interest the radio part (PCB and components) of the mentioned device

Sincerely,

Magneti Marelli S.p.A.

