

Mike Kuo

From: wklo@ccsemc.com.tw
Sent: April 30日 2004年 Friday 2:02 AM
To: Mike Kuo
Cc: Lai, Harris (E-mail); Scott Wang; CCS-Taiwan, Ting (E-mail)
Subject: 回信 : FW: PRO-NETS TECHNOLOGY CORPORATION, FCCId:RXZ-WCB61RL-001, AN04 T3876

Hi Mike,

Here are our replies to your questions.

Notice_content

Question #1: Page 57 of EMC test report with peak reading above average limits. Please provide average measurement.

Ans #1: The average measurement data is provided. Please refer to the revised test report.

Question #2: section 7.7 (page 59) indicates the EUT was plug-in Host PC via USB port. This device is equipped with PCMCIA interface, how the device is able to plug into USB portion of Host computer.

Ans #2: There are typos in Sec. 7.7 (Page 59). Revision is made. Please refer to the revised test report.

Sar portion :

Question #3: System validation (page 14) , body liquid was used vs body sar but the head simulating liquid was indicated. Please make necessary correction.

Ans #3: Correction is made. Please refer to Page 14 of the revised SAR test report.

Question #4: Page 17 and 18 of SAR data summary , what is antenna " 1 " for 802.11g OFDM modulation. Is it Antenna A or B ?

Ans #3: Antenna A and Antenna B are specified. Please refer to Pages 17 & 18 of the revised SAR test report.

Question #5: Page 57 , 63 of SAR data plots indicate the frequency is tuned to 2472MHz which does not agree with SAR test data summary and the highest channel investigated. Please submit SAR test data for these two configuration with channel tuned to 2462MHz.

Ans #3: SAR test data are re-submitted. Please refer to the revised SAR test report.

User Manual :

Question #6: Page 9 of user manual provides the option for the end user to select the country which may cause this device to be operated in the unauthorized frequency channels. Product compliance to operate within authorized channel shall not depend on the user selection. Please address this issue.

5/7/2004

Ans #3: The option of "Country Selection" is removed. Please refer to the revised user manual.

Best Rgds,
WK

Mike Kuo <MKUO@CCSEMC.com>

收件人: "CCS-Taiwan, Ting (E-mail)" <ting@ccsemc.com.tw>, "CCS-Taiwan, Wklo (E-mail)" <wklo@ccsemc.com.tw>

2004/04/27 09:57 AM

副本抄送: "Lai, Harris (E-mail)" <harris@ccsemc.com.tw>, Scott Wang <SWang@CCSEMC.com>

主旨: FW: PRO-NETS TECHNOLOGY CORPORATION, FCC Id:RXZ-WCB61RL-001, AN04 ??? ?T3876

-----Original Message-----

From: CERTADM

Sent: Monday, April 26, 2004 6:57 PM

To: Mike Kuo

Subject: PRO-NETS TECHNOLOGY CORPORATION, FCC Id:RXZ-WCB61RL-001, AN04T3876

Notice_content

Question #1: Page 57 of EMC test report with peak reading above average limits. Please provide average measurement.

Question #2: section 7.7 (page 59) indicates the EUT was plug-in Host PC via USB port. This device is equipped with PCMCIA interface, how the device is able to plug into USB portion of Host computer.

Sar portion :

Question #3: System validation (page 14) , body liquid was used vs body sar but the head simulating liquid was indicated. Please make necessary correction.

Question #4: Page 17 and 18 of SAR data summary , what is antenna " 1 " for 802.11g OFDM modulation. Is it Antenna A or B ?

Question #5: Page 57 , 63 of SAR data plots indicate the frequency is tuned to 2472MHz which does not agree with SAR test data summary and the highest channel investigated. Please submit SAR test data for these two configuration with channel tuned to 2462MHz.

User Manual :

Question #6: Page 9 of user manual provides the option for the end user to select the country which may cause this device to be operated in the unauthorized frequency channels. Product compliance to operate within authorized channel shall not depend on the user selection. Please address this issue.

Best Regards

5/7/2004

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.