
SparkLAN Communications, Inc

8F., No.257, Sec. 2, Tiding Blvd., Neihu District, Taipei City 11493, Taiwan.

Tel: 886-2-2659-1880 / Fax: 886-2-2659-5538

POA for Change in ID of equipment

Date: 2013/5/13

Federal Communications Commission
7345 Oakland Mills Road
Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: RYK-WUBA171GN

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by SparkLAN Communications, Inc will establish a new FCC ID under RYK grantee code for the purpose of marketing.

The original grant to M4Y with FCC ID: M4Y-ZCN722MV1 will remain in effect.

An authorization letter by M4Y is attached.

Per 2.933(b)

The original identification is: FCC ID: M4Y-ZCN722MV1

The original granted date is: 08/15/2011

The equipment is electrically identical. The original test results are applicable and representative of this changed device External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Label and Location Info

Sincerely,

Applicant's company name : SparkLAN Communications, Inc
Applicant's company address : 8F., No.257, Sec. 2, Tiding Blvd., Neihu District, Taipei City
11493, Taiwan.
Signature : 
Job Title and Dept. : Celia Hsu / Executive Vice President
E-Mail : celia.hsu@sparklan.com
Tel. : 886-2-2659-1880
