

RE: Signal Technologies Corporation FCC ID: S2ZRTC2400

1. The co-location of antennas statement is missing from the user's manual. Please revise.

[Please find the revised user manual.](#)

2. The Cover letters are signed by Charlie Stuewe. The Point of Contact registered with the FCC is Magnus Aronsson. Please upload a letter from Magnus Aronsson stating that Charlie Stuewe has authority to act for and in behalf of Magnus Aronsson.

[We recently obtained an approval through FCC using Charlie's signature on the cover letters based on his title of VP and General Manager. Signal Technologies would like to keep Magnus, who is an engineer, as the contact to receive the grant but would like for Charlie as an officer of the company to sign the cover letters. Please let me know if this is not workable.](#)

3. In the test report plots on pages 25 and 26 do not match the data table on page 23. Please explain.

[The marker on these plots appears to have shifted while the data was being taken. The tabular data represents the peak of the waveform shown on the plot.](#)



Tom Tidwell  
NTS Corp.