

50										
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Left	6000	26000	-30.98	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Left	26000	40000	-34.24	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	0.009	0.15	-63.19	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	0.15	30	-73.28	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	30	1000	-52.61	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	1000	3000	-37.73	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	3000	6000	-30.58	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	6000	26000	-30.96	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	L	Edge_1RB_Right	26000	40000	-34.18	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	0.009	0.15	-62.87	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	0.15	30	-71.69	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	30	1000	-52.46	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	1000	3000	-37.63	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	L	Outer_Full	3000	6000	-30.34	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	6000	26000	-30.99	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Outer_Full	26000	40000	-34.49	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	0.009	0.15	-62.48	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	0.15	30	-73.04	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	30	1000	-52.58	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	1000	3000	-37.79	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	3000	6000	-30.64	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	6000	26000	-30.75	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Left	26000	40000	-34.37	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	0.009	0.15	-63.12	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	0.15	30	-72.19	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	30	1000	-52.41	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	1000	3000	-37.74	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	L	Edge_1RB_Right	3000	6000	-30.49	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	6000	26000	-31.08	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	L	Edge_1RB_Right	26000	40000	-34.29	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	0.009	0.15	-62.47	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	0.15	30	-71.64	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	30	1000	-52.71	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	1000	3000	-37.68	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	3000	6000	-30.37	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	6000	26000	-30.90	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Outer_Full	26000	40000	-34.44	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	0.009	0.15	-62.13	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	0.15	30	-73.17	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	30	1000	-52.43	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	1000	3000	-37.71	-13	PASS
N78-3 450-35	30	100	DFT-QPSK	M	Edge_1RB_Left	3000	6000	-30.45	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	6000	26000	-30.87	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Left	26000	40000	-34.47	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	0.009	0.15	-61.85	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	0.15	30	-73.07	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	30	1000	-52.19	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	1000	3000	-37.65	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	3000	6000	-30.60	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	6000	26000	-30.93	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	M	Edge_1RB_Right	26000	40000	-34.49	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	0.009	0.15	-62.36	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	0.15	30	-71.11	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	30	1000	-52.32	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	1000	3000	-37.80	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	M	Outer_Full	3000	6000	-30.50	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	6000	26000	-31.01	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Outer_Full	26000	40000	-34.44	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	0.009	0.15	-62.65	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	0.15	30	-72.48	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	30	1000	-52.37	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	1000	3000	-37.77	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	3000	6000	-30.59	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	6000	26000	-30.98	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Left	26000	40000	-34.34	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	0.009	0.15	-62.52	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	0.15	30	-72.21	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	30	1000	-52.70	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	1000	3000	-37.71	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	M	Edge_1RB_Right	3000	6000	-30.44	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	6000	26000	-30.92	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	M	Edge_1RB_Right	26000	40000	-34.40	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	0.009	0.15	-61.72	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	0.15	30	-72.02	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	30	1000	-52.53	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	1000	3000	-37.77	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	3000	6000	-30.58	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	6000	26000	-30.95	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Outer_Full	26000	40000	-34.47	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	0.009	0.15	-61.50	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	0.15	30	-72.64	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	30	1000	-52.51	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	1000	3000	-37.71	-13	PASS
N78-3 450-35	30	100	DFT-QPSK	H	Edge_1RB_Left	3000	6000	-30.64	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	6000	26000	-30.83	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Left	26000	40000	-34.50	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	0.009	0.15	-62.25	-43	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	0.15	30	-72.57	-33	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	30	1000	-52.57	-23	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	1000	3000	-37.76	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	3000	6000	-30.62	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	6000	26000	-30.95	-13	PASS
N78-3 450-35 50	30	100	DFT-QPSK	H	Edge_1RB_Right	26000	40000	-34.28	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	0.009	0.15	-62.86	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	0.15	30	-72.02	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	30	1000	-52.50	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	1000	3000	-37.78	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	H	Outer_Full	3000	6000	-30.66	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	6000	26000	-30.94	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Outer_Full	26000	40000	-34.43	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	0.009	0.15	-62.27	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	0.15	30	-72.78	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	30	1000	-52.07	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	1000	3000	-37.77	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	3000	6000	-30.51	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	6000	26000	-30.98	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Left	26000	40000	-34.48	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	0.009	0.15	-62.06	-43	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	0.15	30	-72.13	-33	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	30	1000	-52.52	-23	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	1000	3000	-37.65	-13	PASS
N78-3 450-35	30	100	DFT-16QAM	H	Edge_1RB_Right	3000	6000	-30.49	-13	PASS

50										
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	6000	26000	-30.88	-13	PASS
N78-3 450-35 50	30	100	DFT-16QAM	H	Edge_1RB_Right	26000	40000	-34.48	-13	PASS

Test Graphs





























