

Appendix C. SAR measurement setup photos

Test Sample Photos – Parani-UD100



<Sample photo #1>



<Sample photo #2>



<Sample photo #3>



<Sample photo #4>



<Sample photo #5>



<Sample photo #6>



<Sample photo #7>

Body-SAR Configuration



<USB connector Horizontal & Ant Horizontal with extension cable>




<USB connector Horizontal & Ant Horizontal with extension cable>



<USB connector Vertical & Ant Horizontal with extension cable>



<USB connector Vertical & Ant Vertical with extension cable>



<Typical Horizontal Up USB connection & Ant. Horizontal on Laptop>



<Typical Horizontal Up USB connection & Ant. Vertical on Laptop>