TRENDware International Inc.

3135 Kashiwa street, Torrance, CA 90505, USA

TEL: 1-(310)-891-1100 FAX: 1-(310)-891-1111

41

Federal Communications Commission

7435 Oakland Mills Road

Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: SI5WRT372U

To The Commission:

This Change of Identification request applies for a new FCC ID: **S9ZTEW631BRP** as established in 47CFR 2.933(b) for a currently approved device. This application by TRENDware will establish a new FCC ID under TRENDware grantee code for purpose of marketing. The original grant to U-MEDIA Communications, Inc. will remain in effect.

An authorization letter by U-MEDIA Communications, Inc. is attached.

Per 2.933(b)

- 1. The original identification is SI5WRT372U.
- 2. The original grant date is 07/21/2006.
- 3. The equipment is electrically identical. Only the FCC ID number is different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format and location

Sincerely yours.

Wen Tsai Sr. Product Manager TRENDware International Inc.

TEL: 1-(310)-626-6252

FAX: 1-(310)-626-6267 E-mail: w.tsai@trendnet.com