APPENDIX C. Photographs of Setup

Photographs of Conducted Emission Test Configuration

FRONT VIEW




TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C7
Issued Date : Sep. 02, 2004

REAR VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C7
Issued Date : Sep. 02, 2004

SIDE VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C7
Issued Date : Sep. 02, 2004

Photographs of Radiated Emission Test Configuration

FRONT VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C7 Issued Date : Sep. 02, 2004

REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C7 Issued Date : Sep. 02, 2004

FRONT VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C6 of C7 Issued Date : Sep. 02, 2004

REAR VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C7 of C7 Issued Date : Sep. 02, 2004