

## Helen Zhao

---

**Subject:** FW: FW: Sonos Inc., FCC ID: SBVZP002, Assessment NO.: AN05T5323, Notice#1



Revised\_ReportZP8 ZP80\_Guide.pdf  
0.pdf

From: Tom Cokenias  
Sent: Tuesday, December 20, 2005 9:52 PM  
To: Helen Zhao  
Subject: Re: FW: Sonos Inc., FCC ID: SBVZP002, Assessment NO.: AN05T5323, Notice#1

Hi Helen,

Attached please find new report with the info on the RBW and VBW, plus the user manual with the required 15.21 highlighted in yellow.

best regards

Tom

>-----Original Message-----

>From: Compliance Certification Services [mailto:helen.zhao@ccsemc.com]

>Sent: Monday, December 05, 2005 5:25 PM

>To: Helen Zhao

>Subject: Sonos Inc., FCC ID: SBVZP002, Assessment NO.: AN05T5323,

>Notice#1

>

>

>Question #1: The user manual does not contain user information as specified in FCC15.21. Please update the user manual.

>

>Question #2: The test report does not specify measurement procedure, e.g. resolution bandwidth (RBW) and video bandwidth (VBW) setting for radiated emission measurement above 1GHz employing peak and average detector function. Please specify.

>

>Best Regards,

>Helen Zhao

>

>The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee.

>Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.