

Appendix C. Set up Photograph

FCC TEST REPORT Report No. : FR562202

Conducted Emission




FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3 Issued Date : Jul. 25, 2005






SIDE VIEW


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Issued Date : Jul. 25, 2005



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3 Issued Date : Jul. 25, 2005