

In

Dear Tim

When we got the comments from you send, our client found the FCC ID need to change.

So the FCC ID has been changed from SI5-WUB500A to SI5WUB500A.

I have been revised the FCC ID for all documents and uploaded to website.

And the comment has been solved.

Please check.

Thanks for your assistance!

Best Regards

Wendy Liao