

1: The test setup photos show a log periodic antenna being used. Please add that Log Periodic antenna to the equipment list in the report.

The set up photo that we sent before is not correct , and the updated set up photo updated to web site .

2: Also, please confirm that the Bi Conical antenna listed in the equipment list was used for the emissions below 300 MHz.

Yes , we confirmed that the Bi Conical antenna listed in the equipment list was used for the emissions below 300MHz.