



INTERTEK TESTING SERVICES


Report No.: HK11051605-1
Sample No.: 1/2



Timing Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement

INTERTEK TESTING SERVICES

Report No.: HK11051605-1
Sample No.: 1/2



Timing Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement