




# INTERTEK TESTING SERVICES

Report No.: HK10051189-1  
Sample No.: 1/2



Date: 26.MAY.2010 05:46:20

Timing Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement (Pass/Fail)