
## **INTERTEK TESTING SERVICES**


Report No.: HK10051190-1

of )

Sample No.: 1/2



Date: 26.MAY.2010 05:40:30



Date: 26.MAY.2010 05:41:03


## Timming Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement (Pass/Fail)

Code: FCC15C\_c / Effective Date: 04 Aug 2009

## **INTERTEK TESTING SERVICES**

Report No.: HK10051190-1

Sample No.: 1/2



Date: 26.MAY.2010 05:42:43

Timming Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement (Pass/Fail)

Code: FCC15C\_c / Effective Date: 04 Aug 2009