


INTERTEK TESTING SERVICES

Report No.: HK10051191-1
Sample No.: 1/2



Date: 26.MAY.2010 05:28:54

Timing Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement (Pass/Fail)