FCC ID: SQB-NIVISCM42

U.S. Technologies, Inc. FCC Part 22H, 22.901(d) and 24E

Issue Date: September 20, 2005

Report Number: 05-0232 Customer: Nivis, LLC

Model: PCS Transmitter CM-42

## 1.3 Descriptions of Changes in Certified Equipment

There are no changes to the original equipment. Co-location requires a steel barrier to be located between the RF-P9 Module and the SGM 48 Module and 2 steel barriers (one on each side of the modules) between each module and their respective antennas, with a minimum antenna to antenna separation of 101cm.

Refer to sample photo for details.