


Test setup photographs



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Laird Technologies
Model: RMB024
Test #: 140728
Test to: CFR47 (15.247), RSS-210 (DTS)
File: TSup RMB024

SN: PP7
FCC ID#: SQG-RMB024
IC: 3147A-RMB024
Date: August 5, 2014
Page 1 of 3



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Laird Technologies
Model: RMB024
Test #: 140728
Test to: CFR47 (15.247), RSS-210 (DTS)
File: TSup RMB024

SN: PP7
FCC ID#: SQG-RMB024
IC: 3147A-RMB024
Date: August 5, 2014
Page 2 of 3



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Laird Technologies
Model: RMB024
Test #: 140728
Test to: CFR47 (15.247), RSS-210 (DTS)
File: TSup RMB024

SN: PP7
FCC ID#: SQG-RMB024
IC: 3147A-RMB024
Date: August 5, 2014
Page 3 of 3