

Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53





Fig.54


**4 Peak-Average Ratio**

Band	Carrier frequency (MHz)	Channel	BW (MHz)	RB Size	RB Offset	QPSK	16-QAM	64-QAM
4	1710.7	19957	1.4	1	5	Fig.1	Fig.2	Fig.3
	1710.7	19957		6	0	Fig.4	Fig.5	Fig.6
	1732.5	20175		1	5	Fig.7	Fig.8	Fig.9
	1732.5	20175		6	0	Fig.10	Fig.11	Fig.12
	1754.3	20393		1	5	Fig.13	Fig.14	Fig.15
	1754.3	20393		6	0	Fig.16	Fig.17	Fig.18
	1711.5	19965	3	1	14	Fig.19	Fig.20	Fig.21
	1711.5	19965		15	0	Fig.22	Fig.23	Fig.24
	1732.5	20175		1	14	Fig.25	Fig.26	Fig.27
	1732.5	20175		15	0	Fig.28	Fig.29	Fig.30
	1753.5	20385		1	14	Fig.31	Fig.32	Fig.33
	1753.5	20385		15	0	Fig.34	Fig.35	Fig.36
	1712.5	19975	5	1	24	Fig.37	Fig.38	Fig.39
	1712.5	19975		25	0	Fig.40	Fig.41	Fig.42
	1732.5	20175		1	24	Fig.43	Fig.44	Fig.45
	1732.5	20175		25	0	Fig.46	Fig.47	Fig.48
	1752.5	20375		1	24	Fig.49	Fig.50	Fig.51
	1752.5	20375		25	0	Fig.52	Fig.53	Fig.54
	1715	20000	10	1	49	Fig.55	Fig.56	Fig.57
	1715	20000		50	0	Fig.58	Fig.59	Fig.60
	1732.5	20175		1	49	Fig.61	Fig.62	Fig.63
	1732.5	20175		50	0	Fig.64	Fig.65	Fig.66
	1750	20350		1	49	Fig.67	Fig.68	Fig.69
	1750	20350		50	0	Fig.70	Fig.71	Fig.72
	1717.5	20025	15	1	74	Fig.73	Fig.74	Fig.75
	1717.5	20025		75	0	Fig.76	Fig.77	Fig.78
	1732.5	20175		1	74	Fig.79	Fig.80	Fig.81
	1732.5	20175		75	0	Fig.82	Fig.83	Fig.84
	1747.5	20325		1	74	Fig.85	Fig.86	Fig.87
	1747.5	20325		75	0	Fig.88	Fig.89	Fig.90
	1720	20050	20	1	99	Fig.91	Fig.92	Fig.93
	1720	20050		100	0	Fig.94	Fig.95	Fig.96
	1732.5	20175		1	99	Fig.97	Fig.98	Fig.99
	1732.5	20175		100	0	Fig.100	Fig.101	Fig.102
	1745	20300		1	99	Fig.103	Fig.104	Fig.105
	1745	20300		100	0	Fig.106	Fig.107	Fig.108




Date: 6.JUL.2021 21:08:54

Fig.1




Date: 6.JUL.2021 21:09:14

Fig.2




Date: 6.JUL.2021 21:09:33

Fig.3




Date: 6.JUL.2021 21:09:04

Fig.4



Date: 6.JUL.2021 21:09:23

Fig.5



Date: 6.JUL.2021 21:09:42

Fig.6




Fig.7




Fig.8




Fig.9




Fig.10




Fig.11






Fig.12




Date: 6.JUL.2021 21:18:17

Fig.13




Date: 6.JUL.2021 21:18:36

Fig.14




Date: 6.JUL.2021 21:18:55

Fig.15




Date: 6.JUL.2021 21:18:26

Fig.16



Date: 6.JUL.2021 21:18:46

Fig.17



Date: 6.JUL.2021 21:19:05

Fig.18



Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24




Fig.25




Fig.26




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42