

Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54

#### 4 Peak-Average Ratio

Band	Carrier frequency (MHz)	Channel	BW (MHz)	RB Size	RB Offset	QPSK	16-QAM	64-QAM
66	1710.7	131979	1.4	1	5	Fig.1	Fig.2	Fig.3
	1710.7	131979		6	0	Fig.4	Fig.5	Fig.6
	1755	132422		1	5	Fig.7	Fig.8	Fig.9
	1755	132422		6	0	Fig.10	Fig.11	Fig.12
	1779.3	132665		1	5	Fig.13	Fig.14	Fig.15
	1779.3	132665		6	0	Fig.16	Fig.17	Fig.18
	1711.5	131987	3	1	14	Fig.19	Fig.20	Fig.21
	1711.5	131987		15	0	Fig.22	Fig.23	Fig.24
	1755	132422		1	14	Fig.25	Fig.26	Fig.27
	1755	132422		15	0	Fig.28	Fig.29	Fig.30
	1778.5	132657		1	14	Fig.31	Fig.32	Fig.33
	1778.5	132657		15	0	Fig.34	Fig.35	Fig.36
	1712.5	131997	5	1	24	Fig.37	Fig.38	Fig.39
	1712.5	131997		25	0	Fig.40	Fig.41	Fig.42
	1755	132422		1	24	Fig.43	Fig.44	Fig.45
	1755	132422		25	0	Fig.46	Fig.47	Fig.48
	1777.5	132647		1	24	Fig.49	Fig.50	Fig.51
	1777.5	132647		25	0	Fig.52	Fig.53	Fig.54
	1715	132022	10	1	49	Fig.55	Fig.56	Fig.57
	1715	132022		50	0	Fig.58	Fig.59	Fig.60
	1755	132422		1	49	Fig.61	Fig.62	Fig.63
	1755	132422		50	0	Fig.64	Fig.65	Fig.66
	1775	132622		1	49	Fig.67	Fig.68	Fig.69
	1775	132622		50	0	Fig.70	Fig.71	Fig.72
	1717.5	132047	15	1	74	Fig.73	Fig.74	Fig.75
	1717.5	132047		75	0	Fig.76	Fig.77	Fig.78
	1755	132422		1	74	Fig.79	Fig.80	Fig.81
	1755	132422		75	0	Fig.82	Fig.83	Fig.84
	1772.5	132597		1	74	Fig.85	Fig.86	Fig.87
	1772.5	132597		75	0	Fig.88	Fig.89	Fig.90
1720	132072	20	1	99	Fig.91	Fig.92	Fig.93	
1720	132072		100	0	Fig.94	Fig.95	Fig.96	
1755	132422		1	99	Fig.97	Fig.98	Fig.99	
1755	132422		100	0	Fig.100	Fig.101	Fig.102	
1770	132572		1	99	Fig.103	Fig.104	Fig.105	
1770	132572		100	0	Fig.106	Fig.107	Fig.108	




Fig.1




Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8




Fig.9




Fig.10




Fig.11




Fig.12




Fig.13




Fig.14




Fig.15




Fig.16




Fig.17




Fig.18




Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24




Fig.25




Fig.26




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42