





LTE Band 40 subset1 64QAM 5MHz CH-Low, 100%RB




14:08:28 29.11.2021

LTE Band 40 subset1 64QAM 5MHz CH-High, 100%RB




14:11:20 29.11.2021

LTE Band 40 subset1 64QAM 10MHz CH-Low, 1 RB




15:09:10 29.11.2021

LTE Band 40 subset1 64QAM 10MHz CH-High, 1 RB




15:10:38 29.11.2021

LTE Band 40 subset1 64QAM 10MHz CH-Low, 100%RB



15:10:00 29.11.2021


LTE Band 40 subset1 64QAM 10MHz CH-High, 100%RB



15:11:12 29.11.2021




LTE Band 40 subset2 QPSK 5MHz CH-Low, 1 RB




14:28:56 29.11.2021

LTE Band 41 subset2 QPSK 5MHz CH-High, 1 RB




14:34:26 29.11.2021

LTE Band 40 subset2 QPSK 5MHz CH-Low, 100%RB




14:30:33 29.11.2021

LTE Band 41 subset2 QPSK 5MHz CH-High, 100%RB




14:36:10 29.11.2021

LTE Band 40 subset2 QPSK 10MHz CH-Low, 1 RB



14:50:20 29.11.2021


LTE Band 41 subset2 QPSK 10MHz CH-High, 1 RB



14:52:34 29.11.2021




LTE Band 40 subset2 QPSK 10MHz CH-Low, 100%RB




14:51:55 29.11.2021

LTE Band 41 subset2 QPSK 10MHz CH-High, 100%RB




14:53:55 29.11.2021

LTE Band 41 16QAM 5MHz CH-Low, 1 RB




14:29:37 29.11.2021

LTE Band 40 subset2 16QAM 5MHz CH-High, 1 RB




14:35:13 29.11.2021

LTE Band 40 subset2 16QAM 5MHz CH-Low, 100%RB



14:30:05 29.11.2021

LTE Band 40 subset2 16QAM 5MHz CH-High, 100%RB



14:35:37 29.11.2021