

From: "JayKim" <JayKim@estech.co.kr>
To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>
Cc: "Sung-Ryul Kim \ (Estech\)" <bamba2k@estech.co.kr>
Subject: RE: Review of R-TRON, Inc., FCC ID: STERSP-DPP-1900

Hello Timothy,

We uploaded the revised file on your website.
And the response of your comment like as below.

1. revised file uploaded
2. revised confidential letter uploaded - we removed EUT photographs in the confidential letter.
3. revised internal photos file uploaded - we can't separate the attenuator pcb board. So, we can not take a picture the bottom of attenuator pcb board.
4. revised internal photos file uploaded
5. revised tune-up procedure file uploaded
6. The RSP-DPP-1900 system uses the RF modem that already got the FCC approval. The FCC ID of RF modem is "PKRNVWFB2C".
So, R-tron guy said to me that we are very difficult to get the schematic and confidential documents from them.
Please let me know how can we do that in this case.
7. please see the new tune-up procedure file.
8. we uploaded MPE file.
9. we uploaded revised user manual.
10. we uploaded revised schematics.
11. Same as number 6 reason.

Please check them ASAP, and then let me know.
Thanks.

Jay Kim.

>From: Timothy R. Johnson [<mailto:tjohnson@AmericanTCB.com>]
>Sent: Sunday, October 30, 2005 12:45 PM
>To: jaykim@estech.co.kr
...snip...
>NARTE Certified EMC Engineer
>No. EMC-002205-NE
>
>email: tjohnson@AmericanTCB.com
>alternate email: TRJ@adelphia.net