

Dear Mr. Yang,

Please address following issues.

Q#1: The grantee contact person listed on FCC database is Jong Hwa Park but not YONG HOON KANG. Please provide an updated authorization letter and confidentiality request letter to be signed by him.

⇒ I send revised authorization letter and confidentiality request
It is listed Jong Hwa Park

Q#2: The information content in block diagram, operational description and tune up procedure are extracted from the user manual. However, block diagram and operational description are listed for permanent confidentiality. So please either update the confidentiality request letter or provide an updated user manual.

⇒ I send revised user manual and confidentiality request
I removed block diagram from user manual and operational description
Operational description and tune up procedure is not confidential

Q#3: Please confirm if tune up procedure and Parts list will like to be kept for confidentiality. If yes, please update the confidentiality request letter as accordingly.

⇒ I send revised confidentiality request letter
It is listed that part list is confidential but tune up is not confidential

Q#4: According Part 2, FCC ID format should be FCC ID:STESN-CDMA-23 but not FCC REG. NO. : STESN-CDMA-23. Please update the label format.

⇒ I send revised label form
2page, FCC REG. NO. : STESN-CDMA-23 → FCC ID:STESN-CDMA-23

Q#5: Please go over the conducted emission and band edge test results and test plots behind and make sure they are consistent to each other.

⇒ I am sorry I make mistake
I send revised Test report (Page 14,16 Test result , Page 18 Test plot)

Q#6: Please provide two antenna specifications.

⇒ I send antenna specifications

Q#7: One of the MPE calculation result is for Bluetooth as indicated in page 3 which does not agree with application. Please address.

⇒ I send revised MPE report

Q#8: Please provide test setup photos.

⇒ I send Test setup photos

Best Regards,
Lucy Tsai
CCS