

# Appendix II


**Internal Photographs** 



Internal View of EUT-2




#### Page 2 of 17




Internal View of EUT-4




#### Page 3 of 17



Internal View of EUT-6





Internal View of EUT-8



# UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 5 of 17




Internal View of EUT-10




#### Page 6 of 17


Internal View of EUT-11



Internal View of EUT-12




Page 7 of 17




Internal View of EUT-14



Internal View of EUT-15




Internal View of EUT-16




Page 9 of 17 UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-17




Internal View of EUT-18



#### Page 10 of 17


UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.




Internal View of EUT-20



#### Page 11 of 17



Internal View of EUT-22




Page 12 of 17 UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-23



Internal View of EUT-24




#### Page 13 of 17

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.




Internal View of EUT-26







Internal View of EUT-28




Internal View of EUT-29



Internal View of EUT-30



Internal View of EUT-31



UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 17 of 17