


## **Photographs of EUT**






Cerpass Technology Corp. Issued Date : Dec. 24, 2019

Page No. : 1 of 16

Report No.: 1910090








Cerpass Technology Corp. Issued Date : Dec. 24, 2019

Page No. : 2 of 16

Report No.: 1910090








Cerpass Technology Corp.


Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 3 of 16








Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 4 of 16







Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 5 of 16








Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 6 of 16










Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 7 of 16







RF Chip

Cerpass Technology Corp.

Issued Date : Dec. 24, 2019

Page No. : 8 of 16





80 10 60 20 40 30 50 10 500 80 10 e0 60 40 30 50 10 100 80 10 60 60 40 30



Cerpass Technology Corp.


Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 9 of 16









Cerpass Technology Corp. Issued Date : Dec. 24, 2019

Page No. : 10 of 16

Report No.: 1910090








RF Chip

RF Chip

Cerpass Technology Corp.


Issued Date : Dec. 24, 2019


Page No. : 11 of 16





RF Chip







Issued Date : Dec. 24, 2019

Page No. : 12 of 16








Issued Date : Dec. 24, 2019


Report No.: 1910090

Page No. : 13 of 16





Antenna position





Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 14 of 16








Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 15 of 16





Issued Date : Dec. 24, 2019

Report No.: 1910090

Page No. : 16 of 16