




427 West 12800 South  
Draper, UT 84020

## Test Report Annex


### Internal Photographs

<b>FCC ID</b>	SWX-U6EPIW
<b>ISED ID</b>	6545A-U6EPIW
<b>Equipment Under Test</b>	U6-Enterprise-IW
<b>Report Issue Date</b>	May, 18, 2022


<b>Test Specification</b>	<b>Applicant</b>
47 CFR FCC Part 15, Subpart E	Ubiquiti Inc. 685 Third Avenue New York, NY 10017 U.S.A.




DUT Faceplate removed




6G Module removed




Top Heatsink Removed




DUT Disassembled



Main PCB Top EMI can(s) installed




Main PCB Top EMI can(s) removed




Main PCB Bottom EMI can(s) installed







Main PCB Bottom EMI can(s) removed



6G PCB Top EMI can(s) installed



6G PCB Top EMI can(s) removed



6G PCB Bottom