Continental 🟵

Continental Automotive Systems Corporation

29, Siemens-Road, Ichon-City Gyeonggi-do, Korea

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: SY5SMKREN

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Continental Automotive will establish a new FCC ID under Continental Automotive Systems Corporation grantee code for purpose of marketing. The original grant to HUF Korea Limited FCC ID: URT36-414-600 will remain in effect.

An authorization letter by HUF Korea Limited, Inc. is attached.

Per 2.933(b)

- 1. The original identification is URT36-414-600
- 2. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
- 3. The original test results are applicable and representative of this changed device.
- 4. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter External Photos FCC ID label format and location

Sincerely,

Sung-Min Jang / Manager / Continental Automotive