


112808\_3.JPG: PTM210 C, internal (top) view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 1 of 7






112808\_4.JPG: PTM210 C, internal (buttom) view, unmodified sample

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 2 of 7






112808\_11.JPG: PTM210 C, internal (buttom) view, modified sample

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 3 of 7






112808\_5.JPG: PTM210 C, internal view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 4 of 7






112808\_12.JPG: PTM210 C, internal view, modified sample

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 5 of 7






112808\_6.JPG: PTM210 C, PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 6 of 7





112808\_10.JPG: PTM210 C, PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112808E1

 Date of issue:
 04 October 2011
 Order No.:
 11-112808
 page 7 of 7