YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD. 309, 3rd Floor, No.16, Yun Ding North Road, Huli District, Xiamen City, Fujian, China Tel: 86-592-5702000 Fax: 86-592-5702455 Email: chenjl@yealink.com

Date: 2021-12-09

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The RF chip, model QCC5127, which installed in our product Bluetooth Headset, Model: BH72, FCC ID: T2C-BH72, supports BDR (GFSK), EDR (π /4-DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BLE 1M and BLE 2M. The BLE 1M and BLE 2M has been shielded by the manufacturer using the software.

Sincerely,

Signature:

Stonelu

Stone Lu

Vice General Manager