

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.

309, 3rd Floor, No.16, Yun Ding North Road, Huli District, Xiamen City, Fujian, China

Tel: 86-592-5702000

Fax: 86-592-5702455


Email: chenjl@yealink.com

## FCC certification No. Cover Letter


We, YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD., hereby submit justification for placing the FCC certification No. in the associated user's manual.

According to the FCC regulation, the FCC certification No. should be printed on the dongle, but as the dongle are too small to print the label (FCC ID:T2C-BT51A) , it will be moved to the user manual. The details are as below:

- A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



- B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual.

**Label:**

Trade Mark:Yealink


Product Name: Bluetooth USB Dongle

Model :BT51A

This device complies with part 15 of the FCC Rules.

Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.



Stick the label on page 3 of user manual

IC:CAN ICES-3(B)/NMB-3(B)

FCC ID: T2C-BT51A

IC:10741A-BT51A



YEALINK (XIAMEN ) NETWORK TECHNOLOGY CO., LTD.  
309, 3rd Floor, No.16, Yun Ding North Road, Huli District,  
Xiamen City, Fujian, P.R.C  
Made in China

Best regards,

Signature:

Stone Lu  
Vice General Manager