

# FCC ID Label Location

TWO WAY RADIO  
Model: 3208plus  
FCC ID: T4K3208PLUS

518plus,518Turbo,  
518G,518,3208  
518R,3208R,318P



## FCC RF Warning Label



Device must be restricted to occupational use to satisfy FCC RF exposure compliance. See owner's manual for specific operating requirements