

Date: July 23, 2010

Mark Ryan
Senior EMC Engineer
762 Park Avenue
Youngsville, NC 27596

Re: Fluke Ti100, Ti110, Ti125, TiR110, and TiR125 (FCCID: T68-F125 & IC: 6627A-F125)

Mark,

Attached is the English and French manuals for the Ti125 thermography family. The manuals DO NOT contain information about the radio. Also attached is the supplement with the FCC and IC warnings but that information also will not be shipped for some time - see below.


Leaving out the radio information was done because the radio will not be operational until ~September 2012. That is when we expect to have companion radio accessories using the new radio module available for market. Ti125 family products sold prior to accessories being available will have the radio disabled through software.

The "radio" supplement will be shipped with "radio enabled" products and available on-line to all customers once the accessories ship. That supplement will have additional information on the radio operation.

As you can appreciate, we are trying to keep the lid on the role out. Leaving the radio information out of the manual for now is necessary for marketing reasons. The final version of the manual with the transmitter data will be sent to the TCB to be uploaded/updated to the respective authorities.

All models (Ti100, Ti110, Ti 125, TiR110, and TiR125) use identical radio components and layout.

Regards,



Joe Swanzy, PE
Product Evaluation Manager
Fluke Corporation
6920 Seaway Blvd.
(425)446-5626
Everett, WA 98203
USA