


Annex 3: Internal Photographs of the Device under Tests
Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 1
FCC ID: T78-MCD1000
IC: 6656A-MCD1000



Annex 3: Internal Photographs of the Device under Tests


Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 2

FCC ID: T78-MCD1000

IC: 6656A-MCD1000

Radio Module




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 3

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 5


FCC ID: T78-MCD1000

IC: 6656A-MCD1000



Annex 3: Internal Photographs of the Device under Tests
Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 6
FCC ID: T78-MCD1000
IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 8

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 9

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 10

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 11

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 12

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 13

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 14

FCC ID: T78-MCD1000

IC: 6656A-MCD1000




Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 15

FCC ID: T78-MCD1000

IC: 6656A-MCD1000



Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 16

FCC ID: T78-MCD1000

IC: 6656A-MCD1000


Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 17

FCC ID: T78-MCD1000

IC: 6656A-MCD1000



Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 18

FCC ID: T78-MCD1000

IC: 6656A-MCD1000


Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 19

FCC ID: T78-MCD1000

IC: 6656A-MCD1000



Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 20

FCC ID: T78-MCD1000

IC: 6656A-MCD1000

Annex 3: Internal Photographs of the Device under Tests

Mobile Collaboration Device 1000, Model Number: MCD1000, Contains FCC ID: NKRDRCM

Photo # 21

FCC ID: T78-MCD1000

IC: 6656A-MCD1000

