





Rove B4 & Rove B2






















FCC ID: T7HX8667
IC: 4979B-X8667


MODEL: Rove B4
 P/N: 2201-86830-001 N
 DC 5V --- 2A
 S/N: BBYYWWSSSSSS
 [Factory S/N Barcode]

MAC: XXXXXXXXXXXXX
 [Mac address Barcode]

RFPI: 1EEEEXXY00
 [RFPI Barcode]

EU: Plantronics BV, Scorpius 171,
 2132 LR Hoofddorp, NL
 Only use adaptor listed in the user manual
 IEEE 802.3af compliant Class 2





 Made in China






FCC ID: T7HX8667
IC: 4979B-X8667

MODEL: Rove B2
 P/N: 2201-86820-001 N
 DC 5V --- 2A
 S/N: BBYYWWSSSSSS
 [Factory S/N Barcode]

MAC: XXXXXXXXXXXXX
 [Mac address Barcode]

RFPI: 1EEEEXXY00
 [RFPI Barcode]

EU: Plantronics BV, Scorpius 171,
 2132 LR Hoofddorp, NL
 Only use adaptor listed in the user manual
 IEEE 802.3af compliant Class 2





 Made in China