



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

July 6, 2006

RE: Furuno Systems Co., Ltd.

FCC ID: T87SS23BTXXT

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The Bluetooth module appears to be an OEM part. Therefore top and bottom photographs of the BT Module should be provided, including with the shield removed. While this module is permanently mounted, the FCC requires the TX portion to be properly photographed. Please note that Furuno or Taiyo Yuden can likely provide photographs of this module without destroying the sample tested. Additionally, please include a copy of the photograph provided in the operational description as part of the internal photograph exhibit.
- 2) Your response cites the device does not have an open port to connect to a PC. However the block diagram provided cites an RS232 interface as well as the bottom of the unit appears to possibly contain a port and the manual page 64 mentions a data transfer cable. Please explain.\

Previous Comment: The handheld appears to be Class B and also connect to a PC and therefore considered as a PC peripheral. The device does not appear to be DoC approved. Please explain how this device is approved as a PC Peripheral (i.e. DoC'd, Certified, Considered Class A device and therefore verified, etc.). Note that currently the application does not appear to request Certification as a PC peripheral and does not appear to be DoC labeled. Please explain.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.