

HARMAN Becker Automotive Systems GmbH

Becker-Goering-Str. 16
76307 Karlsbad, Germany
Tel. +49.711.901219.0
Fax: +49.711.901219.29



IDC23H – Function SA8155 Declaration

Karlsbad, 24. January 2023

Function SA8155 Declaration

To whom it may concern:

This is to confirm that the LTE function of the equipment listed below will be disabled.

Additionally, the WiFi, Bluetooth, and GNSS functions of the SA8155 are not used in this design. WiFi and Bluetooth are implemented via the 88Q9098, and GNSS via the UBX-M8030.

Product name: IDC23H
Brand: BMW
FCC ID: T8GIDC23H
ID: 6334A-IDC23H

And as evidence thereof, I hereby issue this letter in Karlsbad on 24. January 2023.

Checked & Confirmed by:
Martin Lettner / Project Manager / 23. January 2023

Authorized Signature by:

Stefan Blaschek
Product Compliance Expert
HARMAN Connected Car Division

Harman Becker Automotive Systems GmbH
Becker-Goering-Str. 16
76307 Karlsbad, Germany
Phone: +49 (7248) 71-3382
Email: stefan.blaschek@harman.com
Web: www.harman.com

Simon Vögele
Product Compliance Expert
HARMAN Connected Car Division

Harman Becker Automotive Systems GmbH
Becker-Goering-Str. 16
76307 Karlsbad, Germany
Phone: +49 (7248) 71-3667
Email: simon.voegel@harman.com
Web: www.harman.com

CONNECTED CAR | LIFESTYLE AUDIO | PROFESSIONAL SOLUTIONS | CONNECTED SERVICES

Harman/Becker Automotive Systems GmbH
Geschäftsführung: Markus Helfrich, Oliver Mundle, Peter Radtke, Christian Sobottka
Vorsitzender des Aufsichtsrats: Marko Ferdinand
Sitz der Gesellschaft: Karlsbad | Amtsgericht Mannheim: HRB-Nr. 361395

HARMAN AUTOMOTIVE DIVISION
Harman Becker Automotive Systems GmbH
Becker-Goering-Straße 16
76307 Karlsbad, Germany