

issued by an FCC listed Laboratory Reg. no. 93866. The test site complies with RSS-Gen, file no: IC 3482

Handled by, department
Jonas Bremholt
Electronics
+46 (0)10 516 5438, jonas.bremholt@sp.se

Date 2010-10-15

Reference FX013696-F22

Page 1 (2)

Ericsson AB Mats Falk PDU Radio Base Station

Lindholmspiren 11 417 56 Göteborg

Radio measurements on RRUW 02 B5 WCDMA 850 MHz radio equipment with FCC ID: TA8CKRC11846-2 and IC: 287AB-CW118462

(9 appendices)

Test object

RRUW 02 B5, KRC 118 46/2 Rev. R2F, S/N C823514012

Summary

Standard	Compliant	Appendix	
FCC CFR 47 / IC RS	S-132 Issue 2		
2.1046 / RSS-132 4.4	RF power output	Yes	2
2.1049 / RSS-Gen 4.6.1	Occupied bandwidth	Yes	3
2.1051 / RSS-132 4.5	Band edge	Yes	4
2.1051 / RSS-132 4.5	Spurious emission at antenna terminals	Yes	5
2.1053 / RSS-132 4.5	Field strength of spurious radiation	Yes	6
2.1055 / RSS-132 4.3	Frequency stability	Yes	7
FCC CRF 47 / Industry			
15.111 / RSS-132 4.6	Receiver spurious emissions	Yes	8

Note: Above RSS-132 items are given as cross-reference only. Measurements were performed according to ANSI procedures referenced by FCC and covered by SP's accreditation.

SP Technical Research Institute of Sweden

Electronics - EMC

Christer Karlsson Technical Manager Jonas Bremholt
Technical Officer

SP Technical Research Institute of Sweden

SWEDEN



Date Reference Page 2010-10-15 FX013696-F22 2 (2)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Table of contents

Description of the test object	Appendix 1
Operation mode during measurements	Appendix 1
Test setups	Appendix 1
Purpose of test	Appendix 1
RF power output	Appendix 2
Occupied bandwidth	Appendix 3
Band edge	Appendix 4
Spurious emission at antenna terminals	Appendix 5
Field strength of spurious radiation	Appendix 6
Frequency stability	Appendix 7
Receiver spurious emissions	Appendix 8
External photos	Appendix 9

Date Reference 2010-10-15 FX013696-F22 1(7)

Appendix 1

Description – Test object

IC: 287AB-CW118462

FCC ID: TA8CKRC11846-2

Equipment: WCDMA radio equipment (RRUW) 850 MHz single and multi carrier.

Frequency range: TX: 871.4 – 891.6 MHz

RX: 826.4 – 846.6 MHz

Modulations: QPSK, 16QAM and 64QAM

Nominal output power: Single carrier: 1x 47.8 dBm (1x 60W) Multi carrier: 2x 44.8 dBm (2x 30W) (Maximum)

4x 41.8 dBm (4x 15W)

Channel bandwidth: 4.2 to 5 MHz (configurable in steps of 100/200 kHz) 4.4 to 5 MHz (configurable in steps of 100/200 kHz) Channel spacing:

Nominal power voltage: -48 VDC

Tested channels

	Downlink		Uplink	
Channel	Frequency*	UARFCN	Frequency*	UARFCN
В	871.4	4357	826.4	4132
B+5	876.4	4382	831.4	4157
B+10	881.4	4407	836.4	4182
B+15	886.4	4432	841.4	4207
M	881.6	4408	836.6	4183
T-15	876.6	4383	831.6	4158
T-10	881.6	4408	836.6	4183
T-5	886.6	4433	841.6	4208
T	891.6	4458	846.6	4233

^{*} Frequency in MHz

Operation mode during measurements

Measurements were performed with the test object transmitting the Test models which are defined in 3GPP TS 25.141. Test model 1 (TM1) uses the QPSK modulation only, Test model 5 (TM5) includes the 16QAM modulation and Test model 6 (TM6) includes the 64QAM modulation.

The settings below were found to be representative for all traffic scenarios when several settings with the different modulations, channel bandwidths and the number of carriers were tested to find the worst case setting. These settings were used for all measurements if not otherwise noted.

Single carrier

TM1: 64 DPCH:s at 30 ksps (SF=128)

Multi carrier

TM1: 32 DPCH:s at 30 ksps (SF=128) in each carrier (Two carrier mode)

Channel bandwidth 5 MHz

Conducted measurements

The test object was powered with -48 VDC. All RF conducted measurements were performed with the test object configured for maximum transmit power. All TX measurements were done at the RF A connector and the RX measurements were done on the RF B connector.

2(7)



REPORT

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 1

Radiated measurements

The test object was powered with -48 VDC. All measurements were performed with the test object configured for maximum transmit power. The configuration represents worst case for radiated spurious emission measurements.

The RF output power port was via a RF attenuator connected to functional test equipment for supervision.

The RRUW unit was allocated to the following UARFCN:

Single Carrier: (One carrier configuration)

Single Carrier (one carrier configuration)				
Cell	1	1	1	
Channel	В	M	T	

Multi Carrier: (Two carrier configuration)

		<u> </u>		
Cell	1	2	1	2
Channel	В	B+10	T-10	T

Multi Carrier: (Four carrier configuration)

		, ,		
Cell	1	2	3	4
Channel	В	B+5	B+10	B+15
Channel	Т	T-5	T-10	T-15

Purpose of test

The purpose of the tests is to verify compliance to the performance characteristics specified in applicable items of FCC CFR 47 and Industry Canada RSS-132.

References

Measurements were done according to relevant parts of the following standards:

ANSI 63.4-2003

ANSI/TIA/EIA-603-B-2002

CFR 47 part 2, October 1st, 2009

CFR 47 part 22, October 1st, 2009

3GPP TS 25.141, version 8.9.0

RSS-Gen Issue 2

RSS-132 Issue 2

Date Reference Page 2010-10-15 FX013696-F22 3 (7)

Appendix 1

IC: 287AB-CW118462

FCC ID: TA8CKRC11846-2

Measurement equipment

Measurement equipment	Calibration Due	SP number
Test site Tesla	2010-10	503 881
R&S FSIQ 40	2011-07	503 738
R&S FSQ 40	2011-07	504 143
R&S ESI 26	2011-07	503 292
High pass filter	2011-07	504 199
RF attenuator 30 dB	2011-07	900 229
RF step attenuator	2012-07	503 096
Boonton RF Peak power meter/analyzer	2010-10	503 144
Boonton Power sensor 56518-S/4	2012-02	503 146
Chase Bilog antenna CBL 6111A	2011-10	502 181
EMCO Horn Antenna 3115	2011-01	502 175
μComp Nordic, Low Noise Amplifier	2011-07	504 160
Climate chamber 2	2010-11	501 031
Multimeter Fluke 87	2011-03	502 190
Testo 625, Temperature and humidity meter	2011-08	504 188
Testo 635 temperature and humidity meter	2011-03	504 203

Reservation

The test results in this report apply only to the particular test object as declared in the report.

Delivery of test object

The test object was delivered 2010-08-20.

Test engineers

Tomas Lennhager, Jörgen Wassholm and Jonas Bremholt

Test participants


Christer Hjorth and Ove Nilsson, Ericsson AB



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 1

Test set-up conducted measurements TX



Test object

RRUW 02 B5, KRC 118 46/2 with software CXP 901 6967/3 Rev R1E01 (FCC ID: TA8CKRC11846-2 / IC: 287AB-CW118462)

Functional test equipment


- 1. ERNC SIM 145, BAMS 1000707989
- 2. Fast Ethernet switch, Netgear GSM7224, BAMS 1000838369
- 3. Fast Ethernet switch, Netgear GSM7212, BAMS 1000517292
- 4. Computer, Sunblade Ultra 45, BAMS 1000655789
- Main Unit: 2xRBS 6601 with DU 1: DUW 30 01 KDU 127 161/3 Rev R2A S/N (s)C823356397 and DU 2: DUW 30 01 KDU 127 161/3 Rev R3A S/N (s)C823570214, with Software CXP 901 6967/3, rev. R1E01
- 6. NTP server, Symmetricom SyncServer, BAMS 1000699484
- 7. 10 MHz reference, Symmetricom model 8040, BAMS 1000545314
- 8. Attenuator SP 900 229
- 9. Terminator



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 1

Test set-up conducted measurements RX



Test object

RRUW 02 B5, KRC 118 46/2 with software CXP 901 6967/3 Rev R1E01 (FCC ID: TA8CKRC11846-2 / IC: 287AB-CW118462)

Functional test equipment


- 1. ERNC SIM 145, BAMS 1000707989
- 2. Fast Ethernet switch, Netgear GSM7224, BAMS 1000838369
- 3. Fast Ethernet switch, Netgear GSM7212, BAMS 1000517292
- 4. Computer, Sunblade Ultra 45, BAMS 1000655789
- 5. Main Unit: 2xRBS 6601 with DU 1: DUW 30 01 KDU 127 161/3 Rev R2A S/N (s)C823356397 and DU 2: DUW 30 01 KDU 127 161/3 Rev R3A S/N (s)C823570214, with Software CXP 901 6967/3, rev. R1E01
- 6. NTP server, Symmetricom SyncServer, BAMS 1000699484
- 7. 10 MHz reference, Symmetricom model 8040, BAMS 1000545314
- 8. Attenuator SP 503 096
- 9. Attenuator SP 900 229 with Terminator



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 1

Test set-up radiated measurements



Test object

RRUW 02 B5, KRC 118 46/2 with software (Single carrier) CXP 901 6141/1, rev. R7G04, (Multi carrier) CXP 901 6967/3 Rev R1E01 (FCC ID: TA8CKRC11846-2 / IC: 287AB-CW118462)

Functional test equipment

- ERNC SIM 145, BAMS 1000707989
- 2. Fast ethernet switch, Netgear GSM7224 BAMS 1000838369
- 3. Fast ethernet switch, Netgear GSM7212 BAMS 1000517292
- 4. Computer Sunblade Ultra 45 BAMS 1000655789
- 5. Ethernet/GPIB converter, National Instrument
- 6. CMU 300, R & S, BAMS 1000452891
- 7. Spectrum analyzer, R & S, FSIQ 26, BAMS 1000452890
- 8. Directional coupler
- 9a. Main Unit (Single carrier): 2xRBS 6601 with DU 1: DUW 30 01 KDU 127 161/3 Rev R3A S/N (s)C823474535 and DU 2: DUW 30 01 KDU 127 161/3 Rev R3A S/N (s)C823486741, with Software CXP 901 6141/1, rev. R7G04
- 9b. Main Unit (Multi carrier): 2xRBS 6601 with DU 1: DUW 30 01 KDU 127 161/3 Rev R2A S/N (s)C823356397and DU 2: DUW 30 01 KDU 127 161/3 Rev R3A S/N (s)C823570214, with Software CXP 901 6967/3, rev. R1E01
- 10. NTP Symmetricom SyncServer, BAMS 1000699484
- 11. Symmetricom model 8040, BAMS 1000545314
- 12. Attenuator, Weinschel model 48-30-33 s/n BH8672
- 13. Terminated in 50 ohm
- 14. RET Remote Electrical Tilt unit



Date Reference Page 2010-10-15 FX013696-F22 7 (7)

Appendix 1

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Interfaces:	Type of port:
Power configuration: -48 VDC	DC Power
Antenna port RF A, 7/16 connector, female	Antenna
Antenna port RF B, terminated	Antenna
Test, No cable attached	Test purposes
Xalm, Not supported	Signal
Cross connect RX A, Not supported	Signal
Cross connect RX B, Not supported	Signal
RXA CO-site, Not supported	Signal
ALD Ctrl, Shielded multi-wire connected to RET unit	Signal
Data 1: Optical Interface Link, Single mode opto fibre	Signal
Data 2: Not supported	Signal



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 2

RF power output measurements according to 47 CFR 2.1046/ RSS-132 4.4

Date	Temperature	Humidity
2010-09-02	22 °C ± 3 °C	38 % ± 5 %
2010-09-03	$22~^{\circ}\text{C} \pm 3~^{\circ}\text{C}$	36 % ± 5 %
2010-09-06	$22 ^{\circ}\text{C} \pm 3 ^{\circ}\text{C}$	$42~\%~\pm 5~\%$

Test set-up and procedure

The output was connected to a peak power analyzer with the CDF mode activated.

Measurement equipment	SP number
Boonton RF Peak power meter/analyzer	503 144
Boonton Power sensor 56518-S/4	503 146
Multimeter Fluke 87	502 190
Testo 635, Temperature and humidity meter	504 203

Measurement uncertainty: 0.7 dB

Results

Single carrier: Rated output power level at RF A connector (maximum): 1x 47.8 dBm

Transmitter power (dBm / dB) RMS / PAR			
B M T			
47.9/ 7.0	48.0/7.2		

Multi carrier: Rated output power level at RF A connector (maximum): 2x 44.8 dBm

Transmitter combined power (dBm / dB) RMS / PAR		
B + (B+10) T + (T-10)		
47.7/ 7.5	47.8/ 7.6	

Multi carrier: Rated output power level at RF A connector (maximum): 4x 41.8 dBm

Transmitter combined power (dBm / dB) RMS / PAR	
B + (B+5) + (B+10) + (B+15)	T + (T-5) + (T-10) + (T-15)
47.8 / 8.4	47.8/ 8.3



Date Reference Page 2010-10-15 FX013696-F22 2 (2)

Appendix 2

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Limit

According to CFR 47/ RSS there are no conducted limits at the antenna connector.

CFR \S 22.913/ SRSP-503 5.1: The effective radiated power (ERP) of base transmitters and cellular repeaters must not exceed 500 Watts (57 dBm).

RSS-132: The transmitter output power shall not exceed the limits given in SRSP-503

Complies?	Yes



 $\begin{array}{ccc} \text{Date} & \text{Reference} & \text{Page} \\ 2010\text{-}10\text{-}15 & FX013696\text{-}F22 & 1 \ (1) \end{array}$

Appendix 3

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Occupied bandwidth measurements according to 47 CFR 2.1049/ RSS-Gen 4.6.1

Date	Temperature	Humidity
2010-09-02	$22 ^{\circ}\text{C} \pm 3 ^{\circ}\text{C}$	38 % ± 5 %
2010-09-03	$22 ^{\circ}\text{C} \pm 3 ^{\circ}\text{C}$	36 % ± 5 %

Test set-up and procedure

The measurements were made as defined in §2.1049. The output was connected to a spectrum analyzer. The spectrum analyzer was connected to an external 10 MHz reference standard during the measurements.

Measurement equipment	SP number
R&S FSIQ	503 738
Testo 635, Temperature and humidity meter	504 203

Measurement uncertainty: 3.7 dB

Results

The results are shown in appendix 3.1

Channel Bandwidth 5.0 MHz

	Channel	OBW
Diagram 1	В	4.18 MHz
Diagram 2	M	4.18 MHz
Diagram 3	T	4.17 MHz

Channel Bandwidth 4.2 MHz


	Channel	OBW
Diagram 4	В	3.85 MHz
Diagram 5	M	3.85 MHz
Diagram 6	T	3.86 MHz




FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 3.1











FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 3.1










Page 3 (3)


REPORT

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 3.1









Date Reference Page 2010-10-15 FX013696-F22 1 (1)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 4

Band edge measurements according to 47 CFR 2.1051/ RSS-132 4.5

Date	Temperature	Humidity
2010-09-02	22 °C ± 3 °C	38 % ± 5 %
2010-09-03	22 °C ± 3 °C	36 % ± 5 %
2010-09-06	22 °C ± 3 °C	42 % ± 5 %

Test set-up and procedure

The measurements were made as defined in §22.917. The output was connected to a spectrum analyzer with the RMS detector activated. The spectrum analyzer was connected to an external 10 MHz reference standard during the measurements. A resolution bandwidth of 30 kHz was used up to 3.25 MHz away from the band edges. 30 kHz is <1% of the Emission BW (4.25 MHz between the 26 dB points for 5 MHz nominal BW setting). To compensate for the reduced measurement bandwidth, the limit was adjusted with 1.5 dB to -14.5 dBm up to 1 MHz away from the band edges and with 15.2 dB to -28.2 dBm from 1 MHz to 5 MHz away from the band edges.

Measurement equipment	SP number
R&S FSIQ	503 738
Testo 635, Temperature and humidity meter	504 203

Measurement uncertainty: 3.7 dB

Results

The results are shown in appendix 4.1

Single carrier: Diagram 1: B Diagram 2: T

Multi carrier:

Diagram 3: B+(B+5) Diagram 4: T+(T-5)

Limits

The power of any emission outside the frequency band shall be attenuated below the transmitter power (P) by at least $43 + 10 \log P \, dB$.

Complies?	Yes
-----------	-----


Date Reference 2010-10-15 FX013696-F22 1 (4)




FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 4.1









Date Reference F 2010-10-15 FX013696-F22 2

Page 2 (4)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 4.1






Date Reference Page 2010-10-15 FX013696-F22


3 (4)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 4.1









Date Reference Page 2010-10-15 FX013696-F22 4 (4)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 4.1









Date Reference Page 2010-10-15 FX013696-F22 1 (1)

Appendix 5

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Conducted spurious emission measurements according to 47 CFR 2.1051/RSS-132 4.5

Date	Temperature	Humidity
2010-09-02	22 °C ± 3 °C	38 % ± 5 %
2010-09-03	22 °C ± 3 °C	36 % ± 5 %
2010-09-06	22 °C ± 3 °C	42 % ± 5 %

Test set-up and procedure

The measurements were made with a resolution bandwidth of 1 MHz instead of 100 kHz as RSS-132 specifies 1 MHz for equipment with an emission bandwidth of \geq 4 MHz. The output was connected to a spectrum analyzer. First a pre-measurement with activated peak detector was performed. An emission close to or above the limit is measured with activated RMS detector and the RMS measurement result is noted. The spectrum analyzer was connected to an external 10 MHz reference standard during the measurements.

Measurement equipment	SP number
R&S FSIQ	503 738
High pass filter	503 739
Testo 635, Temperature and humidity meter	504 203

Measurement uncertainty: 3.7 dB

Results

The results are shown in appendix 5.1

Single carrier:

Diagram 1: B Diagram 2: M Diagram 3: T

Multi carrier:

Diagram 4: B+(B+10) Diagram 5: T+(T-10)

Remark

The emission at 9 kHz on the plots was not generated by the test object. A complementary measurement with a smaller RBW showed that it was related to the LO feed-through.


Limits


The power of any emission outside the frequency band shall be attenuated below the transmitter power (P) by at least $43 + 10 \log P \, dB$.

Complies?	Yes
-----------	-----

Date Reference Page 2010-10-15 FX013696-F22 1 (5)


FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 5.1






Date Reference Page 2010-10-15 FX013696-F22 2 (5)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 5.1







Date Reference Page 2010-10-15 FX013696-F22 3 (5)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 5.1











FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 5.1






The emissions around the carriers are within the operating frequency band






FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 5.1



The emissions around the carriers are within the operating frequency band



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 6

Field strength of spurious radiation measurements according to 47 CFR 2.1053/RSS-132 4.5

Date	Temperature	Humidity
2010-08-23 to 2010-08-27	23 °C ± 3 °C	48 % ± 5 % to 54 % ± 5 %

Test set-up and procedure

The test site is listed at FCC, Columbia with registration number: 93866. The test site also complies with RSS-Gen, Industry Canada file no.:IC 3482A-1.

The transmitter was modulated with pseudorandom data during the measurements. The antenna port "RF A" was connected to functional test equipment outside the test chamber for signal monitoring. Antenna port "RF B" was terminated with a 50 ohm load.

The measurements were performed with both horizontal and vertical polarization of the antenna. The antenna distance was 3 m.

- 1. A pre-measurement was first performed:
- 2. In the frequency range 30 MHz-15 GHz the measurement was performed in power with a RBW of 1 MHz. A propagation loss in free space was calculated. The used formula was.

$$\gamma = 20 \log \left(\frac{4\pi D}{\lambda} \right)$$
, γ is the propagation loss and D is the antenna distance.


- 3. The measurement procedure was as the following:
- 4. The pre-measurement was first performed with peak detector. The EUT was measured in eight directions and with the antenna at three heights, 1.0 m, 1.5 m and 2.0 m.
- 5. Spurious radiation on frequencies closer than 20 dB to the limit is scanned 0-360 degrees and the antenna is scanned 1-4 m for maximum response. The emission is then measured with the RMS detector and the RMS value is reported, frequencies closer than 10 dB to the limit measured with the RMS detector were measured with the substitution method according to the standard.

Measurement equipment	SP number
Semi anechoic chamber	503 881
R&S ESI 26	503 292
Software: R&S EMC 32, ver.8.20.1	503 745
Chase Bilog antenna CBL 6111A	503 182
EMCO Horn Antenna 3115	502 175
MITEQ Low Noise Amplifier	504 160
HP 1-15 GHz	504 199
Temperature and humidity meter, Testo 625	504 188



FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 6

The test set-up during the spurious radiation measurements is shown in the picture below:



Results

Single carrier

Single Carrier			
	Spurious emission level (dBm)		
Frequency (MHz)	Vertical	Horizontal	
30-15 000	All emission > 20 dB below limit	All emission > 20 dB below limit	
	Measurement uncertainty 4.7 dB		

Multi carrier

	Spurious emission level (dBm)		
Frequency (MHz)	Vertical	Horizontal	
30-15 000	All emission > 20 dB below limit	All emission > 20 dB below limit	
	Measurement uncertainty 4.7 dB		

Limits

The power of any emission outside the frequency band shall be attenuated below the transmitter power (P) by at least $43 + 10 \log P \, dB$.

Complies?	Yes
-----------	-----

 $\begin{array}{ccc} \text{Date} & \text{Reference} & \text{Page} \\ 2010\text{-}10\text{-}15 & FX013696\text{-}F22 & 1 \ (1) \end{array}$

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 7

Frequency stability according to 47 CFR 2.1055/ RSS-132 4.3

Date	Temperature (test equipment)	Humidity (test equipment)
2010-09-06 to 2010-09-10	$21-23^{\circ}\text{C} \pm 3^{\circ}\text{C}$	35-43 % ± 5 %

Test set-up and procedure

The measurement was made per 3GPP TS 25.141. The output was connected to a spectrum analyzer. The spectrum analyzer was connected to an external 10 MHz reference standard during the measurements.

Measurement equipment	SP number
R&S FSQ 40	504 143
Testo 635, Temperature and humidity meter	504 203
Climate chamber 2	501 031

Results

Nominal Voltage -48 V DC Maximum output power at mid channel (M)

Test conditions		Frequency error (Hz)
Supply voltage DC (V)	T (°C)	1 5 \ /
-48.0	+20	-6
-55.2	+20	-6
-40.8	+20	-6
-48.0	+30	-4
-48.0	+40	-5
-48.0	+50	-4
-48.0	+10	-5
-48.0	0	-6
-48.0	-10	-5
-48.0	-20	-4
-48.0	-30	-8
Maximum freq.	error (Hz)	8
Measurement un	ncertainty	$< \pm 1 \times 10^{-7}$

Limits (according to 3GPP TS 25.141)

The frequency error shall be within \pm 0.05 PPM \pm 12 Hz (56.1 Hz).

Com	plies?	Yes



Date Reference Page 2010-10-15 FX013696-F22 1 (1)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Appendix 8

Receiver spurious emissions measurements according to 47 CFR 15.111/ IC RSS-132, section 4.6.

Date	Temperature	Humidity
2010-09-06	$22^{\circ}\text{C} \pm 3 ^{\circ}\text{C}$	42 % ± 5 %

Test set-up and procedure

The measurements were performed according to ANSI C63.4.

Measurements were performed on the receiver antenna terminal (RF B). The measurement is first performed with peak detector. Emission on frequencies close to or above the limit is remeasured with quasi-peak detector (average detector above 1000 MHz).

Measurement equipment	SP number
R&S FSQ 40	504 143
Testo 635, Temperature and humidity meter	504 203

Result

The results are shown in appendix 8.1:

Diagram 1	В
Diagram 2	M
Diagram 3	T

Note: During the measurement on the RX port RF B the combined TX/RX port RF A was terminated into 50 ohm, the TX was active in single carrier mode transmitting TM1.

Remark

The emission at 9 kHz on the plots was not generated by the test object. A complementary measurement with a smaller RBW showed that it was related to the LO feed-through.

Limit


The power of any spurious output signals appearing at the antenna terminals must not exceed -57 dBm (2 nanowatt).


Emission below limit?	Yes

Date Reference Page 2010-10-15 FX013696-F22 1 (3)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 8.1









Date Reference Page 2010-10-15 FX013696-F22 2 (3)


FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 8.1






Date Reference Page 2010-10-15 FX013696-F22 3 (3)

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462 Appendix 8.1







FCC ID: TA8CKRC11846-2

Date Reference 2010-10-15 FX013696-F22

Appendix 9

Page 1 (2)

External photos of EUT

IC: 287AB-CW118462



Rear side



Right side



Left side





Date 2010-10-15

Reference FX013696-F22

Page 2 (2)

Appendix 9

FCC ID: TA8CKRC11846-2 IC: 287AB-CW118462

Bottom side



Top side

