## Roku, Inc.

## **Declaration of Product Modifications**

This is to request a Class II permissive change for FCC ID: TC2R1001, originally granted on 02/22/2012. and for IC ID: 5959A-R1001, originally grantedon 02/24/2012.

The major change filed under this application is:

Change #1: Add memory size of SDRAM.

Change #2: Change the manufacturer of the oscillator, the oscillation frequency is identical.

(See the figure below) New Original RN2 C205 208 HD D WRF\_RFIN WRF\_RFOUT B1 WRF\_RFIN WRF\_RFOUT L14 L14 C4 C4 2.4nH BCM 2.4nH BCM × F2 G2 C711 C711 10pF T EXT. SLEEP, CLK EXT. SLEEP, CLK OSCIN OSCOUT D7 D6 OSCIN OSCOUT R625 R625 WRF\_TCXO\_IN WRF\_TCXO\_VI B7 WRF\_TCXO\_IN WRF\_TCXO\_VE EXT\_PWM\_REQ EXT\_PWM\_REQ MU AVSS MU AVSS C62 C62 osci BCM43362KUBG BCM43362KUBG

Sincerely,

Greg Garner / Director of Hardware Engineering Roku, Inc.

12980 Saratoga Avenue Suite #D Saratoga California United States 95070