FCC ID: TE7T2UH

Description of Permissive Change

The report is prepared for FCC class II permissive change. The device hardware and digital

circuitry are identical with original certified. The differences compared with original report

are listing as below:

1. Converting the DTS filing from 15.247 to 15.407 under new rule

2. Updating U-NII-3 filing to under new rule.

3. The device does not support TDWR.

4. The device, which approved under the Old Rules will not be marketed, imported or sold

to United States during the time after June 1, 2016.

5. Updating software and not affecting the RF parameter. We had used new software to

test DFS and upload report to you.

Please refer to test repots for more details about the test items.

Andrea Hsia

Senior Specialist

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232 ext. 1628

Fax: 886-3-3270892

Email: andrea.hsia@tw.bureauveritas.com

Data: 2016-09-08

Reference no.: RF151030C10