

Doug Noble

From: webrobot@americantcb.com
Sent: Monday, September 26, 2005 12:00 AM
To: dnoble@americantcb.com
Cc: whgraff@americantcb.com; murban@americantcb.com; marianne@americantcb.com
Subject: MESSAGE/ccssz/TE7WR54XG_ATCB002730

From: Mr. Wong Eric (ccssz) mailto:eric.wong@cn.ccsemc.com; eric.wong@tw.ccsemc.com

Hello,

Please find our replies below upon your latest comment, thanks!!

1. The image you'd seen on the pg21 doesn't shown the restore by the manufacturer. In fact, the software is locked for only the manufacturer can choosing the region, furthermore all the major setting is restored before placing into the market.

2. Please refer to the latest report, on pg4 we have added the info of the antenna assembly, FYI.

Thank you!!

Eric 0926