



FCC Warning Statement and location

4 July 2005

TRL Compliance Services Ltd
Long Green
Forthampton
Gloucester
GL19 4QH
UK

RE: FCC Warning Statement and location

FCC ID: TFT-RM100

The warning statement is included in the RM100 user manual under section 2, FCC statement and reads as follows:

Warning !

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

Thank you for your attention to these matters.

Yours faithfully
MaxID

Gerhardt Mynhardt
President

Copyright ©2005 MaxID Limited, All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior permission of MaxID.

MaxID Limited, Quattro House, Lyon Way, Frimley, Surrey GU16 7ER, United Kingdom
Phone: +44 (0) 1276 80 4498, Fax: +44 (0) 1276 80 4499, URL: www.maxidcorp.com