

4

3

	•					
ITLE LABEL I PANEL DISPLAY						
ATERIAL SEE NOTES			GENERAC MATL SPECIFICATION	SURFAC	NINT Ce finish I/A	
ize B	CAGE NO	DWG NO	100	0000893	3 ^{REV} G	
CALE	1.000	WT-KG	[.2]	SHEET	1 of 1	
				1		

АГ

[SERIAL NUMBER BARCODE] = MUST BE SCANNABLE BARCODE OF SERIAL NUMBER.

1) [SERIAL NUMBER] = MUST ALWAYS START WITH PZD FOLLOWED BY 10 DIGITS

В

Α