

REPORT NO: 11U13782-1 DATE: May 4, 2011 FCC ID: TLZ-NH931 IC: 6100A-NH931

14. ANTENNA LOCATIONS AND SEPARATION DISTANCES






REPORT NO: 11U13782-1 DATE: May 4, 2011 FCC ID: TLZ-NH931 IC: 6100A-NH931

15. TEST SETUP PHOTOS








ENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 6
This report shall not be reproduced except in full, without the written approval of UL CCS.

REPORT NO: 11U13782-1 DATE: May 4, 2011 FCC ID: TLZ-NH931 IC: 6100A-NH931



END OF REPORT